


Okuma OSP-U100L CNC System

K+S adds repair & testing capabilities for Okuma MIV drives to their wide breadth of testing capabilities of drives, PLCs, Robotics, Terminals and other industrial component repairs.

Major Repairable Components Include

Model Series	Unit Type
MPSXX	Power Supply Units
MIV0XA-3-VX	Spindle Drive Units
MIV0XA-1B5	Single Servo Drive Units
MIV0X0XA-1-B5	Dual Axis Servo Drive Units

**** X will vary by size**



K+S Services core belief is to provide best in class quality repairs at a competitive price through full refurbishment and system testing. We achieve this high standard by developing in-house closed loop test capabilities that test each repair to meet or exceed the OEM specifications. After the unit is repaired and fully refurbished, these systems are used to simulate how the unit will operate when placed back into service. Each repaired unit comes with a detailed failure analysis / test report letting you know why the unit failed and any recommended preventative measures to stop it from happening in the future.